

# Corrected Figure 1: Paul McMahon VK3DIP Wideband Return Loss Bridge

*Amateur Radio*, August 2008, page 11

Note that the 4 wires close to the "Z reference" connector should be connected!

